

To: Way, Steven[way.steven@epa.gov]; Matt Francis[m.francis@erllc.com]
Cc: Allen Sorenson[allen.sorenson@state.co.us]
From: Christoph Goss
Sent: Thur 6/26/2014 1:40:50 PM
Subject: RE: gold king mine - information

Hi Steve

That sounds terrific. Congratulations for finding the miner. Eyewitness accounts are key.

I will adjust the steel sets beyond the portal for 10x10.

Christoph

-----Original Message-----

From: Way, Steven [mailto:way.steven@epa.gov]
Sent: Wednesday, June 25, 2014 7:49 PM
To: Christoph Goss; Matt Francis
Cc: Allen Sorenson
Subject: Re: gold king mine - information

Christoph. - according to a former miner who worked underground in the 90s; I spoke with him this evening here are some of his observations:

1. 10 ft x 10 ft tunnel
2. First 100 ft required only a few sets (3 or 4 as recalled).
3. Next 600 ft on drift was good rock ("baldheaded") no sets.
4. At 700 ft they drove around a collapse for 100 ft and back on drift.
5. The air was good bec upper level were open.
6. Water was only seeping in at minor rates; no structures. (However the Am Tnl was not yet plugged.)

This is all good news.

Steve